


# Bond Inspection

Submitted by: mdwaters\_annapolis

Submitted time: Aug 17, 2021, 12:59:29 PM

Location

**Lat: 38.95118 Lon: -76.49831**



Address

**745 annapolis neck**

Date of Inspection

**Aug 17, 2021, 9:31:00 AM**

Site Pictures



site\_pictures-20210817-133511.jpg



site\_pictures-20210817-133736.jpg



site\_pictures-20210817-133831.jpg



site\_pictures-20210817-134312.jpg



site\_pictures-20210817-134430.jpg



site\_pictures-20210817-134759.jpg



site\_pictures-20210817-134920.jpg



site\_pictures-20210817-135039.jpg



site\_pictures-20210817-135715.jpg



site\_pictures-20210817-140339.jpg



site\_pictures-20210817-140400.jpg



site\_pictures-20210817-140420.jpg



site\_pictures-20210817-142645.jpg

Notes from inspection

**Touch up construction entrance 2**

**Recommend adding millings to edge of road.**

**Clean up dirt by inlet protection outside of site.**

**Touch up inflow to sediment trap and touch up corner of trap.**

**Sediment trap in middle of site, clean straw out of inflow.**

**Berm by single family homes loop compromised sediment left the site. The area will need to be addressed. Citation will be issued.**

**All traps look to be in good working order**