

E & S Inspection Survey

Submitted by: mdwaters_annapolis

Submitted time: Nov 3, 2021, 9:56:26 AM

Address

745 annapolis neck

Location of site

Lat: 38.95036 Lon: -76.49608



Date of Inspection

Nov 3, 2021, 8:55:00 AM

Site Type

Development

Development or Commercial



Development Inspection Images



development_inspection_images-20211103-125535.jpg



development_inspection_images-20211103-130839.jpg





dev.jpg



dev.jpg



dev.jpg



dev.jpg

Notes

- Repair rills between sediment basin and trap on the south side of the site.**
- Turbid water is coming out of traps west of the single family homes. The downstream area of the sediment trap on the south side of the site has less turbid water.**
- Repairs to the rills by the mb area have been completed.**
- Add stone to the inflow to the trap furthest west on site.**
- Silt fence was patched along annapolis neck road in two places pointed out yesterday.**